

## Repair Kit for KT300 50HZ

Repair Kit: 809707 00BM

Description	Part Number	Quantity
--O-RING2-227	050227 0VIT	1
--O-RING2-245	050245 0VIT	2
V-BELT 4/3VX-900 BAND	051088 0000	1
--HEX SOCKET HD CAP SCREW 5/16-18 X 3/4	052469 STNY	21
BEARING LOCKNUT N-09	054098 0000	1
SLEEVE BEARING 1-7/8	054110 A000	2
BALL BEARING SRFS 45MM	054115 0000	1
--RETAINING RING 2.00 EXTERNAL	064032 00ST	1
SHAFT SEAL SEAT CI 1-7/8	065098 0000	1
SEAL HEAD ASSY, VITON, 1-7/8	065219 0000	1
DISCHARGE VALVE ASSEMBLY 1-1/2	066161 A000	7
BOX PACKAGING 28"X20"X12"	18877-282012	1
TUBE PACKAGING 3" X 9"	18878-0309	1
TUBE PACKAGING 3" X 18"	18878-0318	1
TUBE PACKAGING 4" X 24"	18878-0424	1
INSTRUCTION SHEET-KT300-PREVENT	2020-0300-2	1
HSSS CENTER WALL LOCKING	802505 A000	3
PIN CENTERWALL LOCKING	802506 A000	3
RING SS BACKUP T00300	803422 A000	1
BEARING BACKUP-RING	803423 A000	1
SIGHT GLASS (PLEXIGLASS)	804192 A000	1
GASKET SIGHT GLASS	804193 A000	1
GASKET SEP COV T00300	807636 B000	1
REPL GASKET V DK COV T0300C	808475 B000	1
GASKET CYL-SEP T00300	807392 B000	1

Updated: 10/6/2015