



TUTHILL
Vacuum & Blower Systems

4840 West Kearney Street, P. O. Box 2877
Springfield, Missouri USA 65801-2877
Tel 417 865-8715 800 825-6937 Fax 417 865-2950

KMBD 850/1200/1600/2000/2700 Repair & Maintenance Kit

The following list of parts, headed by Tuthill Vacuum & Blower Systems Model Number, are the recommended spare parts to overhaul the unit.

Prices quoted are Ex Works, Springfield, MO USA. Minimum order \$50.

Belt Drive, Slinger Seal Booster Kit - P/N 29212 (Old P/N 809061 00BM)

<u>Description</u>	<u>Part Number</u>	<u>Quantity</u>
Gear Lock Plate	55325	2
Ball Bearing	10999-D	2
Roller Bearing	29252	2
Timing Gear Shim	55357	1
Gear Key	11200	2
Cap Screw	90295-100	1
Cap Screw	92241-050	6
Lockwasher	5879	2
Ball Bearing	21964	1
Lock Plate	11057	6
Lock Plate	10925	2
Cap Screw	90295-175	1
O-Ring	29361-129	1
Mechanical Seal	11449	1
O-Ring	29361-028	1
O-Ring	29361-338	1
O-Ring	29361-037	1

The following part(s) are listed for reference only and are not a part of the repair kit:

Gear Assembly	29605	1
---------------	-------	---

11/2004 dt