



Excellence at work. Excellence in life.

Repair Kit for KT850

Repair Kit: 820085 0850

Description	Part Number	Quantity
BOX PACKAGING 36"X36"X36"	18877-363636	1
TUBE PACKAGING 2" X 9"	18878-0209	1
TUBE PACKAGING 3" X 18"	18878-0318	1
TUBE PACKAGING 4" X 24"	18878-0424	1
TUBE PACKAGING 4" X 36"	18878-0436	2
INSTRUCTION SHEET-KT850-GASKET	2020-0850-13	1
GASKET SIGHT GLASS	804193 A000	1
GASKET,SEP COV T00850	807461 B000	1
GASKET,CYL-SEP T00850	807460 C000	1
GASKET,BTM PL T00850	807561 C000	1
GASKET,TOP PL T00850	807462 A000	1
GASKET, FLG T00850	807559 A000	1
GASKET, OIL PUMP T00850	808391 A000	1
--O-RING2-245	050245 0VIT	2
REPL GASKET, V DK COV T0850C	808473 B000	1

Updated: 7/22/2014 SR