



Excellence at work. Excellence in life.

Repair Kit for KT150

Repair Kit: 820101 0150

| Description | Part Number | Quantity |
|---------------------------|-------------|----------|
| VIBRAMOUNT KIT KT150 | 809855 A000 | 1 |
| --STUD 3/8X16/2 | 052554 OSTZ | 4 |
| VIBRAMOUNT GREEN RD-2-380 | 074491 0000 | 4 |
| VIBRAMOUNT KIT DWG KT150 | 809855 A001 | 1 |

Updated: 7/22/2014 SR